




Front Elevation

LB-05 Load Bearing Beam
Internal & External

RF-01
Cementies

Augered Piles & Needle
Beams

CS-05 Crack
Stitches Internal /
External Full Height
As Shown To Match



Internal Crack Stitches to Be
Drilled Into Triangular Chimney
Brest.

Side Elevation

TRAC Structural Ltd

Providing Solutions For Masonry Repair
23 Belmont Road Stourbridge Central B56 5DQ
Tel: 0117 924 0224 Fax: 0117 924 6574

Whiteway Farm
Museum Store

| | | |
|-------|------------|--|
| 11/00 | SHC | |
| | 21.3.01 | |
| | TSP E42 D1 | |